



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

ENGINEERING CHANGE REQUEST

ECR 45

Date Opened:	9/9/20 9:09 AM	Requested By:	Drouin, Steven
Type:	Tooling/DSK/GSE Drawing Change	Requester*:	Villeneuve, Jonathan
Priority:	Medium	DE Approver*:	Shepherd, David
Status:	Under Review	DM:	Lee, Michael
Reason:		Responsible Engineer:	Fuentes, Roberto
Expense:	0	ECR Specialist:	Drouin, Steven
Target Date:	8/25/20 12:00 AM	ECR Lead*:	Drouin, Steven
Execution Date:			
ECR Approval No:			
RE (R&D):		**BRIEF DESCRIPTION**:	C10-23K
Status Note:		DESCRIPTION/ ADR CONTENT**:	Correct the gap between the two mate's C10-23K and C10-1

CUSTOMER APPROVALS

Customer	Customer Visible	Customer Approval Required	*	Customer Approved
----------	------------------	----------------------------	---	-------------------

PARTS

Part No	Rev	Part Status	Name	Type	Customer Part	Special Comments	Documents
C10-1		On hold	Side Plate Solenoid Side	Sub-assembly			C10-1 rev 9.PDF C10-1_C10-2 deviation Sept 05, 2018.pdf
C10-23K		On hold	Stationary Keeper	Finished Good			

INVENTORY DISPOSITION

Part No Revision	Material No	Current Inventory Qty	Purchasing On-Order Qty	Qty Scheduled for Production
C10-1		7 *	0 *	3 *
C10-23K		6 Quarantine	0 *	6 Stop Current Production

ACCOUNTING JOBS

Accounting Job No	Type	Group	Status
SE CAD Red Barn	Sustain Engineering		Active

EFFECTS

Effect Group	Effects
2. ECR Lead Assessment - Impacted Docs & Output	Drawing Change Required (C10-23K Correct the gap between the two mate's C10-23K and C10-1)
3. ECR Lead Assessment - Status During ECR	UR - Full Under Review (C10-23K)
4. Production Type	In-house production
5A. ECR Lead Assessment - MINOR Changes	Correction of drawing errors (Correct the gap between the two mate's C10-23K and C10-1)
6A. Production Impact	Update/Create CNC Program (update C10-23K program to new REV)
7. Final Impacts	Paperwork Update (Correct the gap between the two mate's C10-23K and C10-1 drawing update), Parts Must Comply (C10-23K)
9. Sustaining Cost Grouping	Poor Quality (C10-23K)